

EPS SSR-5

POWER BUS LOSS: RPDA Z13B (Includes RPCMs Z13B A and B)

ACTION	EQUIP/FUNCTION LOST	CREW INDICATION	NOTES
<p>Power On PCU PCS Z1: EPS RPCM Z14B B</p> <p>sel RPC 15 cmd Close</p>	<p>1</p> <p>RPCM Z13B A (Type VI) RPCM Z13B B (Type V)</p> <p>SPDA Z13B Htr SPDA Z14B Htr CMG 1 Ext Htr CMG 4 Ext Htr PCU 2 Htr DDCU Z13B Htr DDCU Z14B Htr EEATCS Non-op Htr A-1</p> <p>CMG 2 CMG 3</p> <p>PCU 1</p> <p>S-Band SASA S-Band XPDR S-Band BSP KU-Band SGTRC KU-Band SGANT</p>	<p><u>Caution Messages:</u></p> <p><u>Advisory Messages:</u> RPCM Z13B_A Loss of Comm - Z1 RPCM Z13B_B Loss of Comm - Z1</p> <p><u>Telemetry:</u></p> <p>PCS Z1: EPS Z1:EPS</p> <p>RPCM Z13B A - not Active RPCM Z13B B - not Active</p>	<p>① EEATCS, CMG, and PCU heaters are not redundant; possible loss of equipment. PCU is powered to provide some heat.</p>